

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424 Line 105
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER S 18 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933 & 1943
ELEVATION 3908.452/3908.522 ^{USGS} ^{NGS} (ft/meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION GOOD MARK STAMPED: TT 3908 S18 1933

REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 0.7 mi NE of, 235 ft SW of 12 ft x20 ft x 4 ft granite boulder on north side of road with eyebolt cemented in top, 225 ft NE of large broken granite boulder on SE edge of road, 36 feet SE of centerline of the highway, 8 feet south of 36-inch pine tree, in granite boulder about 1 foot lower than the road. A USGS bronze tablet stamped "TT 3908 S18 1933."

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

CSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER 19+91.72 (USBPR) QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933
ELEVATION 3890.708 (ft/meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION SFNF MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

All likely spots for this BM were searched, and no sign of the BM was found. It is unlikely that it still exists. Most survey marks in this area have been removed or destroyed.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

CSC-178

REPORT ON CONDITION OF SURVEY MARK

H20700
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 22 QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933 and 1943
ELEVATION USGS 3977.197 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3976.790 (ft./meter)
CONDITION SFNF MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

There has been much construction and improvement at Yosemite Lodge since this BM was established. The mark seems to lie about where a small man-made pool now exists. The area was searched, but no sign of the BM was found.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

H20702
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 10
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 23 QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933 and 1943
ELEVATION USGS 3985.722 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3985.674 (ft./meter)
CONDITION SFNF MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

This mark is described as being both east of the northeast column and south of the southeast column. Both locations were thoroughly searched and no sign of the mark was found. It lies in the main visitor area of YNP and could have been removed.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

HR0703

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 10
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER 3977 B 1919 (Sta. no. 55) QUAD NUMBER 437 Line 4
LATITUDE _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ " YEAR ESTABLISHED 1933 & 1943
ELEVATION USGS 3977.498 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3977.466 (ft/meter) MARK STAMPED: _____
CONDITION SFNF

REMARKS or REVISED DESCRIPTION:

The written descriptions of this BM refer to outdated landmarks and there is no way to accurately locate this BM. The area at "back of Ahwahnee Hotel" was searched, but there is now no road there; and no sign of a BM or a large flat-topped rock was found.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

HR0704

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 10
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 26 QUAD NUMBER 437 Line 4
LATITUDE _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ " YEAR ESTABLISHED 1933 & 1943
ELEVATION USGS 3976.598 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3976.560 (ft/meter) MARK STAMPED: _____
CONDITION SFNF

REMARKS or REVISED DESCRIPTION:

The entire sidewalk in front of the Ahwahnee Hotel was searched, and there was not any sign of a BM at the location described. The original front of the hotel is now the side of the hotel, but the BM is simply not there.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

H20713
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 20 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933 & 1943
ELEVATION USGS 3970.290 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3970.300 (ft/meter) MARK STAMPED: _____
CONDITION SFNF
REMARKS or REVISED DESCRIPTION:

A thorough search of the area described was conducted, but no sign of the BM or the witness post was found. Since it was set flush with the ground, it MAY be buried now. The location was not pinpointed enough to start digging.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. CSC-178

REPORT ON CONDITION OF SURVEY MARK

H20699
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 21 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933 and 1943
ELEVATION USGS 3969.086 By: USGS NGS OTHER _____ (Name of agency)
C&GS 3969.064 (ft/meter) MARK STAMPED: _____
CONDITION SFNF
REMARKS or REVISED DESCRIPTION:

The area was thoroughly searched and there is no sign of the BM or the witness post. The area is currently undergoing road improvements, and it has undoubtedly been worked before. There is very little chance of this BM still existing.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. CSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 24 QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3980.117 (ft) meter By: USGS NGS OTHER _____
CONDITION GOOD MARK STAMPED: TT 3980 S24 1933 (Name of agency)

REMARKS or REVISED DESCRIPTION:

Stoneman Bridge, 0.3 mi northwest, thence 0.6 mi east on bike path,
~~XX~~
90 feet east of culvert under bike path, 40 feet east of bridle path
crossing, 27 feet south of centerline bike path, in concrete monument
projecting 1" above ground, bronze tablet stamped "TT 3980 S24 1933."

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421 Line 104
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER S 19 QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933 & 1943
ELEVATION USGS 3952.571 (ft) meter By: USGS NGS OTHER _____
CONDITION GOOD MARK STAMPED: TT 3952 S19 1933 (Name of agency)

REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 2.5 mi northeast of on Northside Dr; 3.6 mi west of
Stoneman Bridge on Northside Dr, 25 feet north of centerline of
road, at the northeast end of a meadow, at a sharp curve in the road,
0.5 feet north of a white concrete witness post, 0.5 feet south
of an overhanging 6-inch fir tree. A USGS standard disk, stamped
"TT 3952 S19 1933" and set in the top of a concrete post set flush
with the ground.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER 72+60.05 (BPR) QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3976.509 (ft)meter By: USGS NGS OTHER _____
CONDITION GOOD MARK STAMPED: 72+60.05 0 00
3976.04 1926
REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 1.3 mi east of on Northside Drive, 105 feet NE of intersection of dirt road heading north, 27 feet NW of centerline of the road, on 2 inch galvanized iron pipe projecting 1 foot above ground; USBPR bench mark, brass cap stamped "72+60.05 0 00 3976.04 1926."

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86
Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER 84+34.74 (USBPR) QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3964.101 (ft)meter By: USGS NGS OTHER _____
CONDITION SFNF MARK STAMPED: _____
REMARKS or REVISED DESCRIPTION:

The written description described the precise location of this BM. The location is in line of current road construction. The area has been worked by heavy equipment and there is definately no BM in the described location.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD. DATE 11-13-86
Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER SBM 3996.37 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933
ELEVATION 3996.37 (ft./meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION SFNF MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

The description of this SBM places it at the present location of a Pac+Bell communication building, or at least in its parking lot. There is definately no granite rock there with a bolt in it.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86
Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER BM 3982.519 (USBPR) QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933
ELEVATION 3982.519 (ft./meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION SFNF MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

The description of this BM is precise. The described location falls either in the paved intersection itself or the well-worn walkways in downtown Yosemite Village. There is no chance of this BM still existing.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86
Marks found in good condition need not be reported unless description is inadequate. Please prepare in triplicate. GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER SBM 3975.69 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933
ELEVATION 3975.69 (ft/meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION GOOD MARK STAMPED: USGSBM

REMARKS or REVISED DESCRIPTION:

Stoneman Bridge, 0.3 mi northwest, thence 0.2 mi east along bike path, at Ahwahnee Bridge over Merced River, center of 16th curbstone on NW curb; copper nail with washer stamped "USGSBM".

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER SBM 3978.72 QUAD NUMBER 437 Line 4
LATITUDE _____ ° _____ ' _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ ° _____ ' _____ " YEAR ESTABLISHED 1933
ELEVATION 3978.72 (ft/meter) By: USGS NGS OTHER _____ (Name of agency)
CONDITION GOOD MARK STAMPED: chiseled cross

REMARKS or REVISED DESCRIPTION:

Stoneman Bridge, 0.3 mi northwest, thence 0.4 mi east on bike path, at east end of Sugar Pine Bridge, about 125 east of east end of bridge, 14 feet south of centerline of bike path, on large letter "S" on cast iron manhole cover; chiseled cross.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
 STATION NAME and/or NUMBER SBM 3952.467 (BPR) QUAD NAME Yosemite NW
 QUAD NUMBER 437 Line 4
 LATITUDE _____ ° _____ ' _____ "
 LONGITUDE _____ ° _____ ' _____ "
 ELEVATION 3952.467 (ft)meter
 CONDITION GOOD

TYPE of MARK: BM TRAV. TRIANG. DOPPLER
 YEAR ESTABLISHED 1933
 By: USGS NGS OTHER _____ (Name of agency)
 MARK STAMPED: no stamping

REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 1.9 mi east of on Northside Drive, at Y-junction of road to El Capitan Bridge, 300 feet W of E face of W abutment of El Capitan Bridge, 57 feet north of centerline intersection, on 2 inch galvanized iron pipe projecting 0.5 feet above ground; USBPR bench mark, brass cap unstamped, all painted flourescent orange.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
 STATION NAME and/or NUMBER See Below QUAD NAME Yosemite NE
 QUAD NUMBER 437 Line 4
 LATITUDE _____ ° _____ ' _____ "
 LONGITUDE _____ ° _____ ' _____ "
 ELEVATION See Below (ft)meter
 CONDITION SFNF

TYPE of MARK: BM TRAV. TRIANG. DOPPLER
 YEAR ESTABLISHED 1933
 By: USGS NGS OTHER _____ (Name of agency)
 MARK STAMPED: _____

REMARKS or REVISED DESCRIPTION:

All the marks listed below were 1½ inch wrought iron pipe with cemented copper nail (or iron bolt) and washer. A thorough search was conducted for each one, but no traces of any SBMs were found. At times, the EXACT location could be found from the written description. Other times, the location was a bit vague. In all cases there was no sign of the SBMs. I believe they were consciously removed as "eyesores" or "hazards".

- SBM 3963.16
- SBM 3971.54
- SBM 3958.57
- SBM 3962.06
- SBM 3961.27
- SBM 3969.06
- SBM 3974.13
- SBM 3961.72
- SBM 3963.81
- SBM 3968.62
- SBM 3973.21
- SBM 3988.55
- SBM 3989.02
- SBM 3988.35
- SBM 3977.81
- SBM 3995.26
- SBM 3991.70

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER 0+87.06 (BPR) QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3883.425 (ft/meter) By: USGS NGS OTHER _____
CONDITION GOOD MARK STAMPED: 0+87.06 408+77.06 (Name of agency)
3883.04 1926
REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 0.02 mi NW of, 102 feet NW of NW end of SW parapet, 26 feet north of centerline of northern leg of triangle road, on 2 inch galvanized iron pipe projecting 1.0 ft above ground: USBPR bench mark, brass cap stamped "0+87.06 408+77.06 3883.04 1926."

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424
QUAD NAME Yosemite NW
STATION NAME and/or NUMBER See Below QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION See Below (ft/meter) By: USGS NGS OTHER _____
CONDITION SFNF MARK STAMPED: _____ (Name of agency)

REMARKS or REVISED DESCRIPTION:

All the marks listed below were 1½ inch wrought iron pipe with cemented copper nail (or iron bolt) and washer. A thorough search was conducted for each one, but no traces of any SBMs were found. At times, the EXACT location could be found from the written description. Other times, the location was a bit vague. In all cases there was no sign of the SBM. I believe they were consciously removed as "eyesores" or "hazards.!"

SBM 3880.04 SBM 3958.56
SBM 3892.94 SBM 3956.33
SBM 3918.47 SBM 3951.66
SBM 3920.86 SBM 3959.56

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER 166+47.20 (BPR) QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3958.237 (ft/meter) By: USGS NGS OTHER _____
CONDITION Disturbed MARK STAMPED: 166+47.20 3957.72 (Name of agency)

REMARKS or REVISED DESCRIPTION:

Fohono Bridge, 3.1 mi east on Northside Dr; 3.0 west of Stoneman Bridge on Northside Dr, 20 feet SE of centerline of road, on 2 inch galvanized iron pipe, USBPR bench mark, brass cap painted orange stamped "166+47.20 3957.72".

The brass cap on this BM can be wiggled a little and is loose, but it seems it would still hold its original elevation.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

CSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421
QUAD NAME Yosemite NE
STATION NAME and/or NUMBER 112+15.31 (USBPR) QUAD NUMBER 437 Line 4
LATITUDE _____ TYPE of MARK: BM TRAV. TRIANG. DOPPLER
LONGITUDE _____ YEAR ESTABLISHED 1933
ELEVATION 3965.486 (ft/meter) By: USGS NGS OTHER _____
CONDITION Disturbed/Destroyed MARK STAMPED: _____ (Name of agency)

REMARKS or REVISED DESCRIPTION:

The iron pipe and cap were found at the described location, but they are located in a ditch and have obviously been hit and bent by road working equipment. The pipe is solid in the ground, but bent at a distinct angle. The elevation is gone.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

CSC-178