

REPORT ON CONDITION OF SURVEY MARK

STATE Calif. COUNTY Mariposa QUAD NAME Betch Betchy S.E.
 STATION NAME and/or NUMBER 6603 B QUAD NUMBER N37119442 USGS line
 LATITUDE _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
 LONGITUDE _____ " Quad 455
 ELEVATION 6603.952 ft./meter By: USGS NGS OTHER _____ (Name of agency)
 CONDITION _____ MARK STAMPED: 6603 B

REMARKS or REVISED DESCRIPTION:

This bench mark was SET in 1986 at the location of the present bridge. After this search and during a discussion with the superintendent of trail maintenance it was determined that the original bridge had been washed out in the winter of 1957/58 and a new bridge put in at a different location. This BM is shown on the 1958 special edition "Map of Yosemite Valley" about 300 feet below the bridge as it existed in 1958. It has been sketched on the 1955 photos GS-VJS 2-23 There is a possibility that the BM can be found if the abutments for the old bridge can be found.

SUBMITTED BY: David E. Reed AGENCY USGS DATE 8/26/86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

STATE Calif. COUNTY Mariposa QUAD NAME Betch Betchy S.E.
 STATION NAME and/or NUMBER F 7852 QUAD NUMBER N37119442 USGS line
 LATITUDE _____ " TYPE of MARK: BM TRAV. TRIANG. DOPPLER
 LONGITUDE _____ " Quad 455
 ELEVATION 7852.655 ft./meter By: USGS NGS OTHER _____ (Name of agency)
 CONDITION Good MARK STAMPED: F 7852 1905

REMARKS or REVISED DESCRIPTION:

This bench mark was reported not found in 1956. New description is as follows: Up Yosemite Falls Trail northeast to Snow Flat; at the top of the saddle between Lehamite Creek and Porcupine Creek, 70 feet northeast of the trail fork to Indian Ridge, 15 feet northwest of the trail fork to Snow Creek, cemented in the top of a 3 feet by 5 foot boulder, an aluminum tablet stamped F 7852 1905 and about 2 feet higher than the trail fork.

SUBMITTED BY: David E. Reed AGENCY USGS DATE 8/26/86