

REPORT ON CONDITION OF SURVEY MARK

HR0706  
MAPPING CENTER

STATE Ca COUNTY Mariposa QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER 3983 B 1919 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3983.809 By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
ELEVATION C&GS 3983.762 (ft/meter)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

It is difficult to establish where culvert 357 was. The only "guardwall" in the area does not go over a culvert today. It is also difficult to see how the end of a guardwall could be underground. Yet all likely areas were thoroughly searched and no sign of a BM or a witness post was found.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON PERMANENT SURVEY MARK MAP INFORMATION OFFICE

HR0710

STATE Ca COUNTY Mariposa QUADRANGLE Yosemite NE  
QUOTE PRIMARY REFERENCE \_\_\_\_\_ NGS# 37 119 421 Line 104  
USGS # 437 Lines 1 & 3  
(Direction and distance)

DESIGNATION { LISTED 27 S 3964  
STAMPED 3964 B 1905 27 S TYPE OF MARK: BM  TT \_\_\_\_\_ TRIANG. \_\_\_\_\_  
CONDITION \_\_\_\_\_ ESTABLISHED BY \_\_\_\_\_  
Lat. \_\_\_\_\_ Disturbed  1905, 1933 USGS  USBR   
Long. \_\_\_\_\_ Destroyed  1943 USC&GS  State GS   
Elev. 3964.789 feet Not Found  USNPS  USNFS   
3965.189 GOOD USGLO  USBLM   
3964.803 (Other)

Please prepare in triplicate.

REMARKS OR REVISED DESCRIPTION:

Sentinel Bridge in Yosemite Valley, SPOF sign at south end of, 400 feet east on Southside Dr; Yosemite Chapel, 400 feet east on Southside Dr, 29 feet south of centerline road, top of large granite rock, 3 feet higher than the road, a USGS aluminum disk stamped "3964 B 1905 27S".

SUBMITTED BY Jamie Schubert DATE 12-3-86  
TITLE \_\_\_\_\_ AGENCY USGS, NMD

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER BM S 9 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION 3989.615 (ft) meter By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

This BM was Not Found in 1958. The description is precise, and the probable exact spot of the BM was located, but there is no sign of it. It is gone.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER SBM 3969.61 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION 3969.61 (ft) meter By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION GOOD MARK STAMPED: no stamping

REMARKS or REVISED DESCRIPTION:

Pohono Bridge, 4.1 mi east of along Southside Drive; 0.8 mi west of Sentinel Bridge along Southside Dr, 42 feet west of 66 inch cedar tree, 20 feet southeast of centerline road, 14 feet northwest of 10 inch pine tree, 8 feet southwest of 10 inch ~~XX~~ cedar tree, cemented in 1½ inch galvanized iron pipe projecting about 6 inches; iron bolt and washer.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER 22+23.75 (USBPR) QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
ELEVATION 3908.908 (ft/meter) TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF YEAR ESTABLISHED 1933  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

It was difficult to fit the written description to the ground in this area; maybe the road has been changed. The entire stretch of possible road was searched, and there was no sign of this BM. It is probably destroyed like 90% of the others.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424 Line 10  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER S 17 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
ELEVATION 3881.052/3881.050 (ft/meter) TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION GOOD YEAR ESTABLISHED 1933 & 1943  
MARK STAMPED: TT 3881 S17 1933

REMARKS or REVISED DESCRIPTION:

Pohono Bridge, Southwest corner of; 8.9 mi northeast along HWY 140 from the old RR station at El Portal, 25 feet west of the centerline of the road, 10 feet SE of SE end of SW parapet of bridge, 5 feet south of 60-inch pine tree. A USGS standard disk, stamped "TT 3881 S17 1933" and set in the top of a concrete post set flush with the ground.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 12-8-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

NGS# 37 119 421  
 STATE Ca COUNTY Mariposa QUAD NAME Yosemite NE  
 STATION NAME and/or NUMBER See Below QUAD NUMBER 437 Line 3  
 LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
 LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933  
 ELEVATION See Below (ft) meter By: USGS  NGS  OTHER \_\_\_\_\_  
 (Name of agency)  
 CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

All the marks listed below were 1½ inch wrought iron pipe with cemented copper nail (or iron bolt) and washer. A thorough search was conducted for each one, but no traces of any SBMs were found. At times, the EXACT location could be found from the written description. Other times, the location was a bit vague. In all cases there was no sign of the SBM. I believe they were consciously removed as "eyesores" or "hazards".

- SBM 4018.63    ·SBM 3970.44    ·SBM 3986.58    ·SBM 3969.20    ·SBM 3976.50
- SBM 4002.40    ·SBM 3971.97    ·SBM 3974.99    ·SBM 3969.71
- SBM 3988.31    ·SBM 3979.92    ·SBM 3968.30    ·SBM 3973.71
- SBM 3980.90    ·SBM 3979.70    ·SBM 3958.39    ·SBM 3962.02
- SBM 3976.63    ·SBM 3980.98    ·SBM 3957.49    ·SBM 3972.53

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

Mail To:  
 U.S. GEOLOGICAL SURVEY  
 NCGIS MS-507  
 RESTON, VA 22092

NGS # 37 119 421 Line 104  
 STATE Ca COUNTY Mariposa QUAD NAME Yosemite NE  
 STATION NAME and/or NUMBER S 10 QUAD NUMBER 437 Line 3  
 LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
 LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
 ELEVATION USGS 3965.922 By: USGS  NGS  OTHER \_\_\_\_\_  
C&GS 3965.894 (ft) meter (Name of agency)  
 CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

The exact location of this BM was located, but the BM was not there. It has either been buried or destroyed by road improvements.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

HR0712  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER S 11 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3964.920 C&GS 3964.926 (ft./meter) By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

A thorough search for this BM was conducted, but no sign of it could be found.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

HR0714  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER S 12 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3972.050 C&GS 3972.144 (ft./meter) By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

A thorough search for this mark was conducted, but no sign of it could be found.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

H207M  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 1  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER S 14 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3976.306 By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
C&GS 3976.377 (ft/meter)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

This mark was reported Not Found in 1956. Another thorough search turned up no sign of this BM.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

H20719  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 424 Line 10  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER S 15 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3961.347 By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
C&GS 3961.416 (ft/meter)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

This mark was reported Not Found in 1956. A thorough search in 1986 found no sign of this BM. There is no 6 foot granite boulder in the area, unless it has been covered by road fill.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON PERMANENT SURVEY MARK

AREA OFFICE

STATE Ca COUNTY Mariposa NGS# 37 119 424 Line 104  
QUADRANGLE Yosemite NW  
QUOTE PRIMARY REFERENCE \_\_\_\_\_ USGS # 437 Line 3  
(Direction and distance)

DESIGNATION { LISTED 180 3953  
STAMPED 3953 1919 TYPE OF MARK: BM X TT \_\_\_\_\_ TRIANG. \_\_\_\_\_

Lat. \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " CONDITION  
Disturbed  1933 USGS  USBR   
Long. \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " Destroyed  1943 USC&GS  State GS   
Elev. 3953.099 feet Not Found  USNPS  USNFS   
USGS 3953.010 GOOD USGLO  \_\_\_\_\_   
USBLM  (Other)

REMARKS OR REVISED DESCRIPTION:

Pohono Bridge in Yosemite Valley, 1.4 mi east on Southside Drive;  
Sentinel Bridge in Yosemite Valley, 3.4 mi west on Southside Dr,  
on outside of curve in road, 25 feet northwest of center of road,  
50 feet southeast center of Merced River, 10 feet west of oak tree,  
top of 10-foot boulder about level with the road, a USGS bronze  
tablet stamped "3953 1919".

SUBMITTED BY Jamie Schubert  
TITLE \_\_\_\_\_  
AGENCY USGS, NMD

DATE 12-3-86

Marks found in good condition need not be reported.

FILL IN ALL AVAILABLE INFORMATION

Please prepare in triplicate.

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 424 Line 104  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER S 16 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE OF MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3914.059 By: USGS  NGS  OTHER \_\_\_\_\_  
C&GS 3914.133 (ft) meter (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS OR REVISED DESCRIPTION:

The area described was thoroughly searched, but no sign of the  
BM could be found. Since the BM was set only 10 feet from the center-  
line of the highway, it has probably been destroyed by road work.

SUBMITTED BY: Jamie Schubert AGENCY: USGS, NMD DATE 11-12-86

REPORT ON CONDITION OF SURVEY MARK

H20715  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER 184+88.00 (USBPR) QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3962.003  
C&GS 3962.111 (ft)meter By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION n SFNF (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

The area of this BM seems to have been graded and had much road work. A thorough search turned up no sign of the BM.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

H20716  
MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421 Line 104  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER S 13 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933 & 1943  
ELEVATION USGS 3969.183  
C&GS 3969.303 (ft)meter By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION SFNF (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

A thorough search turned up no sign of this BM.  
It was reported Not Found in 1956 also.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-12-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178



### REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 424  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER BM S 27 QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
ELEVATION 3912.821 (ft./meter)  
CONDITION SFNF  
TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
YEAR ESTABLISHED 1933  
By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

In the search for this BM, it was assumed that "Concentration plant" referred to a sewage disposal plant. This sewage disposal plant is long abandoned. All likely spots in the area were searched, but there was not enough specifics to start digging for the BM. It could easily have been destroyed while they were decommissioning the plant.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

### REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER 29+48.14 (USBPR) QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "  
ELEVATION 3907.004 3912.821 (ft./meter)  
CONDITION SFNF  
TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
YEAR ESTABLISHED 1933  
By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

The description places this mark in Bridalveil Meadow. The area was thoroughly searched but there was no sign of this BM. Most likely destroyed or removed.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

### REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER 194+09.62 (USBPR) QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION 3974.392 (ft./meter) By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

A thorough search was conducted for this BM, but nothing was found. The description possibly put it in a widened road turnout, or else it has been removed.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

### REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 424  
QUAD NAME Yosemite NW  
STATION NAME and/or NUMBER See Below QUAD NUMBER 437 Line 3  
LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION See Below (ft./meter) By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)  
CONDITION SFNF MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

All the marks listed below were 1½ inch wrought iron pipe with cemented copper nail (or iron bolt) and washer. A thorough search was conducted for each one, but no traces of any SBMs were found. At times, the EXACT location could be found from the written description. Other times, the location was a bit vague. In all cases there was no sign of the SBM. I believe they were consciously removed as "eyesores" or "hazards".

• SBM 3969.64  
• SBM 3978.09  
• SBM 3968.86

• SBM 3937.81  
• SBM 3935.26  
• SBM 3928.02

SBM 3929.57  
SBM 3924.62  
SBM 3915.18  
SBM 3894.12

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178