

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER SBM 3966.14 QUAD NUMBER 437 Line 6  
LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION 3966.14 (ft/meter) By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION SFNF (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

Although the roads have changed and no longer fit the description, a manhole cover was located at the north end of Sentinel Bridge. IF this is the manhole cover in question, new asphalt of a parking lot is laid right up to the metal circumference of the cover, and there is no visible edge of concrete manhole lining.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER S 25 QUAD NUMBER 437 Line 6  
LATITUDE \_\_\_\_\_ " TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ " YEAR ESTABLISHED 1933  
ELEVATION 3966.845 (ft/meter) By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION SFNF (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

The description is totally obsolete, but the intersection described seems to be the one just west of the Bank of America. This is now an open, busy intersection; and all points 15 ft from the intersection are graded. There is no sign of this BM.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS # 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER SBM 3965.09 QUAD NUMBER 437 Line 6  
LATITUDE \_\_\_\_\_ TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ YEAR ESTABLISHED 1933  
ELEVATION 3965.09 (ft/meter) By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION DISTURBED? DESTROYED? (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

There is a manhole cover at the described location, but there is no letter "S" on it. The manhole cover which had the elevation placed on it has been replaced by a new iron manhole cover. The new elevation is probably extremely close to the old one, but not exactly.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

MAPPING CENTER

STATE Ca COUNTY Mariposa NGS# 37 119 421  
QUAD NAME Yosemite NE  
STATION NAME and/or NUMBER SBM 3965.67 QUAD NUMBER 437 Line 6  
LATITUDE \_\_\_\_\_ TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER   
LONGITUDE \_\_\_\_\_ YEAR ESTABLISHED 1933  
ELEVATION 3965.67 (ft/meter) By: USGS  NGS  OTHER \_\_\_\_\_  
CONDITION SFNF (Name of agency)  
MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

The obsolete description places this manhole cover in a meadow. Although all other manhole covers in the level lines were located, no sign was found of this one. Perhaps the wrong area was searched, but it was the most likely area using the given description.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86

Marks found in good condition need not be reported unless description is inadequate.

Please prepare in triplicate.

GSC-178

REPORT ON CONDITION OF SURVEY MARK

NGS # 37 119 421

STATE Ca COUNTY Mariposa QUAD NAME Yosemite NE

STATION NAME and/or NUMBER \*SBMs 3961.82, 3966.72, 3966.95 QUAD NUMBER 437 Line 6

LATITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "

TYPE of MARK: BM  TRAV.  TRIANG.  DOPPLER

LONGITUDE \_\_\_\_\_ ° \_\_\_\_\_ ' \_\_\_\_\_ "

YEAR ESTABLISHED 1933

ELEVATION See above (ft/meter)

By: USGS  NGS  OTHER \_\_\_\_\_ (Name of agency)

CONDITION SFNF

MARK STAMPED: \_\_\_\_\_

REMARKS or REVISED DESCRIPTION:

These three SBMs were all 1½ inch galvanized iron pipe with cemented iron bolt and washer. A thorough search was conducted for each, but no sign of them could be found. As each SBM is in the central use area of Yosemite Valley, around campgrounds and bike paths, they have most likely been purposefully removed or destroyed.

SUBMITTED BY: Jamie Schubert AGENCY USGS, NMD DATE 11-13-86