

## REPORT ON CONDITION OF SURVEY MARK

**STATE** PA

**COUNTY** Lackawanna

**QUAD NAME** Scranton

**STATION NAME and/or NUMBER** 39 JPN

**QUAD NUMBER** 166 Line 17

**LATITUDE** N41° 15' 37"

**TYPE OF MARK** Bench Mark Disk

**LONGITUDE** W075° 35' 46"

**YEAR ESTABLISHED** 1942

**ELEVATION** 1812.856 ft

**EST. BY:** USGS NGS OTHER:

**CONDITION** Good

**MARK STAMPED:** 39 JPN 1942 1813

**REMARKS or REVISED DESCRIPTION:** Station mark recovered in good condition. The mark is 9 ft at 112°(magnetic) from a conspicuous 2.5ft x 1.5ft x 1.5ft boulder; this boulder is on a line between the mark and the point of intersection of the trail and small brook. Reference mark was searched for but not found.

**SUBMITTED BY:** Jennifer K. Maher  
and Richard S. Galas

**AGENCY:** Individual

**DATE** 5/22/2005